

Oil Field Environmental Incident Summary

Incident: 20151130130301 **Date/Time of Notice:** 11/30/2015 13:03

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BLUE BUTTES-MADISON UNIT G-208

Field Name: BLUE BUTTES

Well File #: 10149

Date Incident: 11/25/2015 **Time Incident:** 16:30

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 95

Sec: 8

Qtr:

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Troy Brunsell
3015 16TH ST SW STE 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.2 Mile

Distance Nearest Water Well: 1.2 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	5	Barrels

Recovered	Units
-----------	-------

Followup	Units
5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/4/2016

Clean Up Concluded: 1/22/2016

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

30' by 50' on location, 60' by 80' off location

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time.

Action Taken or Planned:

The well was shut in. A contractor was notified in regard to remediation of the impacted areas.

Wastes Disposal Location: All recovered wastes will be disposed of at an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 11/30/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater pop-off, was not contained according to the report. More followup needed to determine if any oil was recovered. If not, information is needed on how they plan to remediate the area and why the release was reported five days after the incident.

Date: 12/4/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 1:30 p.m. The weather was sunny, 41°F, with wind from the southwest 10-15 mph. The facility is located on federal lands. A small amount of oil came out a vent on the west side of the building. The largest amount of oil came out the south side of building. Oil sprayed onto the pad and also on vegetation that is fenced-off pasture. Small amounts of oil sprayed further south of the fenced area. The cleanup crew and company personnel were at the site. They were getting ready to start the cleanup. A rolloff was on site to contain the impacted soil and vegetation. The lightly sprayed vegetation will be mowed and collected. Confirmation samples will be taken. They will send a copy of results to the NDDoH. They have also been in contact with Bureau of Land Management (BLM) personnel; BLM has oversight since it is BLM land. 47.91226, -102.89935